

# Coupling



## Specification

Product name	Serial number	Inspection items	standards	Inspection result	Inspection conclusion
Right angle coupler	1~8	Deformation resistance	$P=10.0\text{KN}$ $\Delta \leq 7.0\text{mm}$	$\Delta : 3.69\sim 6.08\text{mm}$	Meet the requirements
		Anti destruction of properties	$P=15.0\text{KN}$ Don't destroy	Unverdorben	Meet the requirements
RounT coupler	9~16	Deformation resistance	$P=7.0\text{KN}$ $\Delta \leq 7.0\text{mm}$	$\Delta : 2.14\sim 3.63$	Meet the requirements
		Anti destruction of properties	$P=10.0\text{KN}$ Don't destroy	Unverdorben	Meet the requirements
Butt joint couper	17~24	Tensile properties	$P=3.0\text{KN}$ $\Delta \leq 2.0\text{mm}$	$\Delta : 0.44\sim 1.55\text{mm}$	Meet the requirements